MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:
MONTERO REAR AIR CONDITIONER — SERVICE MANUAL UPDATE

NO.	TSB-89-55-001
DATE	November, 1989
MODEL	1989, 1990 Montero

TSB Revision: TSB-89-55-001

PURPOSE

The 1989 and 1990 Montero Service Manuals contain references to a rear air conditioner. Because this option is not offered on Monteros in the U.S. market, references to it in the Service Manuals should be disregarded.

SERVICE MANUALS AFFECTED

1989 Montero Service Manual, Pages 24-25
-26
-27
-28
-29
-30
-37
-42
-48
-49
-50
-51
-52

1990 Montero Service Manual, Pages 55-30
-31
-32
-33
-34
-36
-47
-53
-56
-57
-60
-62

FILE UNDER: Group 55 Heater, Air Conditioner, and Ventilation in the Dealer Service Information Binder

CIRCULATE TO:
- ☐ SERVICE ADVISOR
- ☐ GENERAL MANAGER
- ☑ SERVICE MANAGER
- ☐ PARTS MANAGER
- ☐ WARRANTY PROCESSOR
- ☑ TECHNICIAN
- ☐ SALES MANAGER

016617

(749)